

Rotating Ground Couplings



- For a good connection to the workpiece to obtain optimal welding performance.
- For rotating workpieces, a ground connection with a rotatable coupling is the safest choice.
- To attach the coupling to the workpiece, special clamps are available, see "Ground Clamps" below.

Ordering Information

NKK 600, max. 600A, 2.2 kg (4.8 lbs.)	0700 004 007
NKK 800, max. 800A, 2.7 kg (5.9 lbs.)	0700 004 001
NKK 1200, max 1200A, 4.0 kg (8.8 lbs.)	0700 004 002
NKK 2000, max 2000A, 7.3 kg (16 lbs.)	0700 004 003



Rotating ground coupling NKK

Ground Clamps for Rotating Workpieces

- K2 or PZ3 ground clamps can be mounted directly onto the rotatable ground coupling to create good contact between the workpiece and the return cable.
- Return clamps can also be used together with the GA 800 handle connection to form a complete ground clamp to handle high current welding on non-rotating workpieces.

Ordering Information

K2 clamp head for NKK 800/1200	0700 004 004
GA 800 handle connection for K2	0700 004 005
PZ3 pole clamp for NKK 2000	0700 004 006



Handle connection GA 800



K2 clamp head



Pole clamp PZ3